County of Riverside

DEPARTMENT OF ENVIRONMENTAL HEALTH

www.rivcoeh.org

SUPPLEMENTAL REPORT TO SAN. FORM # 2616 / OII / 459	_ DATE	8-24-2019
SUBJECT Vons # 2660 - Del:	_ PERMIT NO.	08441
SUPPLEMENTAL REPORT TO SAN. FORM# 2616/011/459 SUBJECT Vons # 2660 - Del: ADDRESS 38995 Sky Canyon Dr. Murrich CA 92563	_ DISTRICT	43
INSPE	CTOR	.Le
REMARKS:		
- This is a follow up inspection to evaluat	e a clos	ed facility,
- This is a follow up inspection to evaluate Vons # 2660 - Veli, due to greate interceptor for with floor sinks / drain, within this deli clogge	uted and	overflowed
with floor sinks / draw, within this deli cloque	d on	8/23/2019.
- Throises of areas intercent and floor	drainsle	into in the
deli unclient ser professional plumber	and po	ze high
pormer and sanitized cleaning of the	floor	Ensich Deli
and packing lot emailed to inspector.	All above	clean-up
- Invoices of grease interceptor promped, floor deli uncleged per professional plumber pormun and sanistruck cleaning of the and parking lot emailed to inspector. Conducted by end of day on 8/23/2018	the luxue	· 45.
- At this re-inspection, the following were obed @ gream interceptor clean & pumper. Parky her overflow	- concrete	clean. without
overflow		
6) glover of such of floor sinh (drains observed. 6) floors + with in deli grouperly chean and so (4) all equipment and otensite chean and	of debris	- No closped
(E) More + with i deli executed also a 1 &	المراقعة المراقعة	
(4) all equipment and utensite clean and	san'th rea	۷
- Deli is approved to open and opente as	usul,	
- Invoice of grean interesting y lumber my	marcal.	and
- manage Acit Law project with the	e - insace	<u> </u>
	 .	
\		<u></u>
RECEIVED BY: ADDIA MAI	<u> </u>	
HORULAY	Office: CANARY-Own	ner